



Product Discontinuation Notification

PCN-Number / Rev / Date 45075 / 1 / 26.08.2022

Category / change type ACEL active components / PDN Discontinuation / MAJOR

Summary Availability of Control Unit IOXP is limited

Motivation, trigger Status of IOXP is changed to discontinued

Details of change The IOXP has been successfully at the market for numerous years. Vendors of main components for the IOXP like output driver, CAN transceiver and voltage regulator have issued PTNs (product termination notification) and the same is expected to happen in the near future for further components like the main controller.

The status of the IOXP will therefore be changed to "discontinued".

At the same time STW announces the ESX.4ct as pin compatible successor for the IOXP including a 32-bit AURIX controller as well as additional features (see attached data sheet - changes in comparison to IOXP are highlighted with red characters).

The delivery of ESX.4ct samples is scheduled for April 2023, start of serial production (SSOP) is envisaged for Sept. 2023.

STW encourages you to transfer your applications to the ESX.4ct or other current controllers. Our sales and support departments look forward supporting you during this transition.

In case you require further IOXP devices within the scope of a last time buy (LTB), please talk to your local sales representative too.

As a result of the additional acquisition costs for components (e.g. material price, storage costs and component qualifying costs), the price for the IOXP may increase. Additionally, in future the warranty period may be limited by the supply conditions of the component manufacturers.

Alert impact PCN of a sub-component (supplier of STW)

Company STW TECHNIC, LP

EOS end of sales (LTB) 30.11.2022

LTD Last time delivery 31.10.2023

Comments / objections to sales.stw@wiedemann-group.com

Feedback expected until 30.11.2022

Comments or objections are expected before, otherwise this PCN/PDN will become effective without further notification.

If you need further assistance, you may also contact your local sales representative or our sales department. STW shall not be held liable if this notification is not correctly distributed within your organization.

Affected Product	STW part number	Customer part number
ESX.ioxp control unit	49860	n.a.
ESX.ioxp control unit	49861	n.a.
ESX.ioxp control unit	49862	n.a.
ESX.ioxp control unit	56126	n.a.



Product Discontinuation Notification

Affected Product	STW part number	Customer part number
ESX.ioxp control unit	57969	n.a.
ESX.ioxp control unit	60682	n.a.
ESX.ioxp control unit	80775	n.a.
ESX.ioxp control unit	93062	n.a.