
## Pin Assignment of Connectors X1 and X2



## Pin Assignment of Connectors X1 and X2



## Connector X1

Pin	Signal Name	Description
1	CAN2_L	CAN bus 2 low
2	CAN1_L	CAN bus 1 low
3	CAN1_H	CAN bus 1 high
4	CAN2_H	CAN bus 2 high
5	-	Not connected
6	ETH1_P1_BRR+	Ethernet 1 port 1 (BroadR-Reach+, 100BASE-T1)
7	ETH1_P1_BRR-	Ethernet 1 port 1 (BroadR-Reach-, 100BASE-T1)
8	-	Not connected

## **Connector X2**

Pin	Signal Name	Description
1	CAN2_L	CAN bus 2 low
2	CAN1_L	CAN bus 1 low
3	CAN2_H	CAN bus 2 high
4	CAN1_H	CAN bus 1 high
5	-	Not connected
6	ETH1_P2_BRR+	Ethernet 1 port 2 (BroadR-Reach+, 100BASE-T1)
7	ETH1_P2_BRR-	Ethernet 1 port 2 (BroadR-Reach-, 100BASE-T1)
8	-	Not connected

-- 1|1