



Product Change Notification

PCN-Number / Rev / Date	44964 / 3 / 02.06.2022
Category / change type	PAEL passive components / MATER Material / MAJOR
Summary	mainconnetor change of ESX.4cl
Motivation, trigger	ESX.4cl change coding of 48 pol mainconnetor chamber (X)
Details of change	Due to obsolescence of a pre-supplier, the main connector of the ESX.4cl has been changed. The change refers to the 48-pole plug chamber. The coding is changed from "gray" to "brown". The corresponding mating connectors on the vehicle side must be changed from 643201318 to 643201319.
Product marking	With the modification the item number will change ESX.4cl.var3 101508 -> 104065 101509 -> 104061 (Debug Version) ESX.4cl.va4 101507 -> 104063 101510 -> 104060 (Debug Version)
Company	STW TECHNIC, LP

If you need further assistance, you may also contact your local sales representative or our sales department.
STW shall not be held liable if this notification is not correctly distributed within your organization.

Affected Product	STW part number	Customer part number
ESX.4cl.var3	101508	n.a.
ESX.4cl.var3 - debug variant	101509	n.a.